


## RECOMMENDED CUTTING CONDITIONS

Work material		Carbon steel, Cast iron, Alloy steel, Pre-hardened steel Cf53, GG25			Work material		Carbon steel, Cast iron, Alloy steel, Pre-hardened steel Cf53, GG25		
Dia. DC (mm)	Neck length LU (mm)	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)	Depth of cut ap (mm)	Dia. DC (mm)	Neck length LU (mm)	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)	Depth of cut ap (mm)
<b>1</b>	<b>4</b>	40000	3000	0.04	<b>3.5</b>	<b>15</b>	20000	3000	0.6
	<b>8</b>	36000	2400	0.03		<b>25</b>	11000	1600	0.15
	<b>12</b>	20000	1000	0.02		<b>35</b>	5500	800	0.06
	<b>16</b>	10000	500	0.005		<b>4</b>	<b>12</b>	18000	3000
<b>1.2</b>	<b>6</b>	40000	3000	0.05	<b>20</b>		12000	2000	0.5
	<b>10</b>	36000	2400	0.04	<b>30</b>		8000	1300	0.2
	<b>12</b>	20000	1200	0.03	<b>40</b>		4200	700	0.08
	<b>16</b>	12000	600	0.01	<b>50</b>		2400	400	0.03
<b>1.5</b>	<b>6</b>	40000	3200	0.06	<b>5</b>	<b>16</b>	14000	2700	1
	<b>12</b>	32000	2400	0.05		<b>25</b>	9500	1800	0.5
	<b>16</b>	16000	1100	0.03		<b>35</b>	6400	1200	0.2
	<b>20</b>	10000	600	0.01		<b>50</b>	3200	600	0.05
<b>1.8</b>	<b>6</b>	40000	3600	0.08	<b>6</b>	<b>20</b>	11000	2200	1.2
	<b>12</b>	32000	2800	0.06		<b>30</b>	8000	1600	0.6
	<b>20</b>	12000	1000	0.02		<b>40</b>	5400	1100	0.25
	<b>25</b>	7000	600	0.01		<b>50</b>	3200	640	0.15
<b>2</b>	<b>6</b>	40000	4000	0.1	<b>8</b>	<b>30</b>	8000	1600	1.6
	<b>12</b>	32000	3200	0.07		<b>50</b>	4000	800	0.5
	<b>16</b>	24000	2400	0.05		<b>70</b>	2000	400	0.2
	<b>20</b>	12000	1200	0.03	<b>10</b>	<b>40</b>	6400	1300	2
	<b>30</b>	5000	500	0.01		<b>60</b>	3200	640	0.6
<b>2.5</b>	<b>8</b>	32000	4000	0.2	<b>80</b>	1600	320	0.3	
	<b>25</b>	9000	1100	0.04	Depth of cut				
	<b>50</b>	2500	300	0.005					
<b>3</b>	<b>8</b>	25000	3600	0.4					
	<b>16</b>	18000	2500	0.2					
	<b>25</b>	12000	1700	0.1					
	<b>30</b>	7000	800	0.05					

DC: Dia.

ap: Depth of Cut in the Axial Direction

- 1) If the depth of cut is shallow, the revolution and feed rate can be increased.
- 2) Cutting conditions may be considerably different due to the overhang (milling depth), depth of cut, and machine tool. Please see the above table as a standard.