

## RECOMMENDED CUTTING CONDITIONS

R (mm)	Alloy steel, Tool steel, Pre-hardened steel X40CrMoV51				Hardened steel (45–55HRC) X40CrMoV51			
	$\alpha \leq 15^\circ$		$\alpha > 15^\circ$		$\alpha \leq 15^\circ$		$\alpha > 15^\circ$	
	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)	Revolution (min <sup>-1</sup> )	Feed rate (mm/min)
R0.05	40000	200	—	—	40000	170	—	—
R0.1	40000	600	40000	400	40000	600	40000	400
R0.15	40000	900	40000	600	40000	900	40000	600
R0.2	40000	1000	40000	700	40000	1000	40000	700
R0.25	40000	1500	40000	1000	40000	1500	40000	1000
R0.3	40000	2000	40000	1500	40000	2000	40000	1500
R0.35	40000	2800	40000	2100	40000	2800	37000	1800
R0.4	40000	2800	40000	2100	40000	2800	35000	1800
R0.45	40000	3200	38000	2200	38000	3000	32000	1800
R0.5	40000	3200	35000	2200	35000	3000	30000	1800
R0.75	40000	3600	30000	2300	32000	3000	25000	1800
R1	35000	3500	25000	2200	28000	2800	20000	1700
R1.5	30000	3400	23000	2200	24000	2600	16000	1500
R2	25000	3400	20000	2200	20000	2600	14000	1500
R2.5	23000	3400	17000	2200	18000	2600	12000	1500
R3	20000	3400	15000	2200	16000	2600	10000	1400
R4	15000	3000	12500	2000	10000	2000	7500	1200
R5	12000	3000	10000	2000	8000	2000	6000	1200
R6	10000	2600	8300	1800	6600	1700	5000	1100

  

Depth of cut	
--------------	--

- 1)  $\alpha$  is the inclination angle of the machined surface.
- 2) If the depth of cut is shallow, the revolution and feed rate can be increased.
- 3) If the rigidity of the machine or the work materials installation is very low, or chattering and noise are generated, reduce the revolution and feed rate proportionately.