

# Cutting data recommendations for shoulder milling cutters

Feed and cutting speed

			Tool length/ correction factor:		Groove milling										
			Length	$f_z$ & $v_c$			$a_p = 1xD$	$a_e = 1xD$							
			Short	1											
			Long	0,9											
			Overlong	0,8											
			Extra long	0,6											
<b>OptiMill-Uni-HPC-Plus   SCM720, 740, 760, 770</b>															
MMG*		Workpiece material		Strength/ hardness [N/mm <sup>2</sup> ] [HRC]	Coolant supply		$v_c$ [m/min]								
					MQL/Air	Dry	$f_z$ [mm/tooth]								
							Diameter of milling cutter [mm]								
							2.00	4.00	6.00	8.00	10.00	12.00	16.00	20.00	
P	P1	P1.1	Structural, free-cutting, case hardened and heat-treated steels, non-alloy	< 700	✓	✓	175	0.013	0.024	0.035	0.044	0.053	0.061	0.075	0.085
	P1	P1.2	Structural, free-cutting, case hardened and heat-treated steels, non-alloy	< 1200	✓	✓	145	0.012	0.023	0.032	0.041	0.050	0.057	0.070	0.080
	P2	P2.1	Nitrided, case hardened and heat-treated steels, alloy	< 900	✓	✓	160	0.013	0.024	0.035	0.044	0.053	0.061	0.075	0.085
	P2	P2.2	Nitrided, case hardened and heat-treated steels, alloy	< 1400	✓	✓	110	0.011	0.020	0.029	0.037	0.044	0.051	0.062	0.071
	P3	P3.1	Tool, bearing, spring and high-speed steels**	< 800	✓	✓	105	0.012	0.023	0.034	0.043	0.051	0.059	0.072	0.082
	P3	P3.2	Tool, bearing, spring and high-speed steels**	< 1000	✓	✓	95	0.012	0.022	0.032	0.041	0.049	0.056	0.068	0.078
	P3	P3.3	Tool, bearing, spring and high-speed steels**	< 1500	✓	✓	85	0.011	0.021	0.030	0.038	0.046	0.053	0.065	0.074
	P4	P4.1	Stainless steels, ferritic and martensitic		✓	✓	70	0.008	0.016	0.023	0.030	0.035	0.041	0.050	0.057
	P5	P5.1	Cast steel			✓	105	0.012	0.023	0.034	0.043	0.051	0.059	0.072	0.082
	P6	P6.1	Stainless cast steel, ferritic and martensitic			✓	70	0.006	0.011	0.016	0.021	0.025	0.028	0.035	0.040
M	M1	M1.1	Stainless steels, austenitic	< 700	✓	✓	50	0.007	0.014	0.020	0.026	0.031	0.036	0.043	0.050
	M1	M1.2	Stainless steels, ferritic/austenitic (duplex)	< 1000		✓	45	0.006	0.012	0.017	0.021	0.026	0.029	0.036	0.041
	M2	M2.1	Stainless/heat-resistant cast steel, austenitic	< 700	✓	✓	50	0.008	0.015	0.022	0.028	0.034	0.039	0.047	0.054
	M3	M3.1	Stainless cast steel, ferritic/austenitic (duplex)	< 1000		✓	50	0.006	0.012	0.017	0.022	0.027	0.031	0.037	0.043
K	K1	K1.1	Cast iron with lamellar graphite (grey cast iron), GJL	< 300	✓	✓	190	0.021	0.040	0.058	0.074	0.088	0.102	0.124	0.142
	K2	K2.1	Cast iron with spheroidal graphite, GJS	< 500	✓	✓	175	0.018	0.034	0.049	0.063	0.075	0.086	0.106	0.121
	K2	K2.2	Cast iron with spheroidal graphite, GJS	≤ 800	✓	✓	145	0.015	0.028	0.040	0.052	0.062	0.071	0.087	0.099
	K2	K2.3	Cast iron with spheroidal graphite, GJS	> 800	✓	✓	80	0.008	0.016	0.023	0.030	0.035	0.041	0.050	0.057
	K3	K3.1	Cast iron with spheroidal graphite, GJV; malleable cast iron, GJM	< 500	✓	✓	125	0.015	0.028	0.040	0.052	0.062	0.071	0.087	0.099
	K3	K3.2	Cast iron with spheroidal graphite, GJV; malleable cast iron, GJM	> 500	✓	✓	120	0.013	0.024	0.035	0.044	0.053	0.061	0.075	0.085

\* MAPAL machining groups

\*\* If the alloy parts Cr, Mo, Ni, V, W in total > 8 % then select the next highest MAPAL machining group.

Roughing		Finishing	
$v_c$ [m/min]	$f_z$ [mm/tooth]	$v_c$ [m/min]	$f_z$ [mm/tooth]
	Diameter of milling cutter [mm]		Diameter of milling cutter [mm]
	2.00 4.00 6.00 8.00 10.00 12.00 16.00 20.00		2.00 4.00 6.00 8.00 10.00 12.00 16.00 20.00
355	0.021 0.041 0.059 0.075 0.090 0.103 0.126 0.145	525	0.034 0.065 0.093 0.119 0.142 0.164 0.200 0.228
290	0.020 0.038 0.055 0.070 0.084 0.097 0.118 0.135	430	0.032 0.060 0.087 0.111 0.133 0.153 0.187 0.213
325	0.021 0.041 0.059 0.075 0.090 0.103 0.126 0.145	475	0.034 0.065 0.093 0.119 0.142 0.164 0.200 0.228
225	0.018 0.034 0.049 0.063 0.075 0.086 0.105 0.120	335	0.028 0.054 0.078 0.099 0.119 0.136 0.167 0.190
210	0.021 0.040 0.057 0.073 0.087 0.100 0.122 0.140	310	0.033 0.063 0.090 0.115 0.138 0.158 0.193 0.221
195	0.020 0.038 0.054 0.069 0.083 0.095 0.116 0.132	285	0.031 0.059 0.085 0.109 0.130 0.150 0.183 0.209
180	0.019 0.035 0.051 0.065 0.078 0.090 0.110 0.125	260	0.029 0.056 0.081 0.103 0.123 0.142 0.173 0.198
145	0.014 0.027 0.039 0.050 0.060 0.069 0.084 0.096	215	0.023 0.043 0.062 0.079 0.095 0.109 0.133 0.152
215	0.021 0.040 0.057 0.073 0.087 0.100 0.122 0.140	320	0.033 0.063 0.090 0.115 0.138 0.158 0.193 0.221
145	0.010 0.019 0.027 0.035 0.042 0.048 0.059 0.067	215	0.016 0.030 0.043 0.055 0.066 0.076 0.093 0.107
95	0.012 0.024 0.034 0.044 0.053 0.060 0.074 0.084	145	0.020 0.038 0.054 0.069 0.083 0.095 0.117 0.133
90	0.010 0.020 0.028 0.036 0.044 0.050 0.061 0.070	135	0.016 0.031 0.045 0.057 0.069 0.079 0.097 0.110
105	0.014 0.026 0.037 0.048 0.057 0.066 0.080 0.092	155	0.021 0.041 0.059 0.075 0.090 0.104 0.127 0.145
95	0.011 0.020 0.029 0.038 0.045 0.052 0.063 0.072	145	0.017 0.032 0.047 0.059 0.071 0.082 0.100 0.114
390	0.036 0.068 0.098 0.125 0.150 0.172 0.211 0.241	570	0.056 0.108 0.155 0.198 0.237 0.273 0.333 0.381
355	0.030 0.058 0.083 0.106 0.128 0.147 0.179 0.205	525	0.048 0.092 0.132 0.168 0.202 0.232 0.283 0.324
290	0.025 0.048 0.069 0.088 0.105 0.121 0.147 0.169	430	0.040 0.076 0.109 0.139 0.166 0.191 0.233 0.267
160	0.014 0.027 0.039 0.050 0.060 0.069 0.084 0.096	240	0.023 0.043 0.062 0.079 0.095 0.109 0.133 0.152
260	0.025 0.048 0.069 0.088 0.105 0.121 0.147 0.169	380	0.040 0.076 0.109 0.139 0.166 0.191 0.233 0.267
245	0.021 0.041 0.059 0.075 0.090 0.103 0.126 0.145	355	0.034 0.065 0.093 0.119 0.142 0.164 0.200 0.228

The specified machining values are guide values.

The optimum data for the respective machining task should be determined during the test or machining.